

shelby american, inc.  
6501 w. imperial hwy.  
los angeles, calif. 90009  
telephone: 213-674-1961  
cable address: shelcobra

*World Manufacturers Champion 1965*  
*United States Manufacturers Champion*  
*1963 • 1964 • 1965*

Service & Warranty Department  
Service Bulletin No. 67-5

March 1, 1967

TO: All Shelby American Dealers

SUBJECT: Brake Squeek, Front Disc Brake Pads, 1967 GT 350  
and GT 500 Cars

Numerous complaints have been received from customers regarding  
squeaky front disc brake pads.

You are advised to replace front disc brake pads on those cars, where  
complaints of brake squeeks have been received, with 390 Mustang  
disc brake pads, Ford part number C5ZZ 2001-B.

Effective with Shelby American vehicle serial number 1422, all  
GT 350 and GT 500 units will be equipped with new type front  
brake pads.

The replacing of front brake pads, where needed, may be performed  
under warranty.

  
Harry Neumann  
Service & Warranty Administrator

HN/hn

*World's Finest Sports and Competition Automobiles*

COBRA

SHELBY G.T. 350

FORD G.T.