Subject: Lug Wrench for Optional Mag Star Wheels, 1967 Models GT350 and GT500

Several reports from dealers and customers indicate that there are a number of vehicles in the field which do not have the correct lug wrench for those cars equipped with the optional Mag Star Wheels.

April 3, 1967

The correct lug wrench to be used in conjunction with the Mag Star wheels carries the following part number: S7MS 17032-B. This is a Shelby part number and must therefore be ordered from Shelby American.

It is suggested that you check your stock of new vehicles equipped with Mag Star wheels for the correct lug wrench. Customers or dealers who do not have the correct lug wrench in their cars may have them replaced under warranty.

Harry Neumann Service and Warranty Administrator

Service Bulletin No. 67-8